

X-FVM100 Fiber Inspection & Cleaning Tools Kit

X-FVM100 Fiber inspection and Cleaning Tools Kit is specially designed for checking and cleaning various ferrules and adapters in FTTH construction and maintenance. It is a very convenient KIT!



X-FVM100 Probe Specifications

Magnification	400X
Resolution Ratio	0.75 um
Display Screen	3.5" TFT-LCD, 960x240 pixels
Power Supply	12.6V Li Battery
Data Storage	4G
Weight (kg)	Probe (0.16); Monitor (0.4)
Dimensions (cm)	Probe (11*4*4); Monitor(17*10*4.5)
Work/Storage	-20°C~+50°C -30°C~+60°C

X-FVM100 Fiber Inspection & Cleaning Tools Kit

Item	Accessories	Quantity
X-FVM100 Fiber inspection & cleaning tools kit	1. FVM-100 probe	1pc
	2. 3.5" TFT-LCD	1pc
	3. 3.7V AC/DX power adapter	1pc
	4. 25-U-M	1pc
	5. 125-U-M	1pc
	6. 25-U-F	1pc
	7. LC-U-F	1pc
	8. CLEP-125-O	1pc
	9. CLEP-25-O	1pc
	10. CLE-BOX	1pc
	11. CLE-BOX REPLACETET	1pc

Tips

Tips Type	Description	
25-U-M	FC/SC/ST/E2000UPC connector	Standard
125-U-M	LC/MU UPC connector	Standard
25-U-F	FC/SC/ST/E2000 UPC bulkhead	Standard
LC-U-F	LC/MU UPC bulkhead	Standard
25-A-M	FC/SC/ST/E2000 APC connector	Optional
125-A-M	LC/MU APC connector	Optional
25-A-F	SC/FC APC bulkhead	Optional
LC-A-F	LC APC bulkhead	Optional

